Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0860

Address:

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: Oliver, Jerry

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone: Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

NOTICE: CERTIFIED FIRM/ RENOVATOR REQUIRIED

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-313-0494

Client Name:

Client ID:

Alt. Client ID: 16016SW-0860

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 5

Measures

	Measure Prac	tice lead safe Weatheri	zation		Componen	ts		i	Inspected
C	Comment								
				LILLIAN WITH THE PROPERTY OF THE PARTY OF TH	Estimated		-1447-1441-1441-1441-1441-1441-1441-144	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Material	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail			£-1	J. January			;	
L									
				Measur	e Sub Total:]	Sub Total:	The state of the s
									1
		ace D1 with Metal insu B low profile threshold		e	Componen	ts			Inspected
	LS/D			e	Componen Estimated			Actual	Inspected
C	LS/D			e Qty	·		Qty		Inspected
<i>C</i>	LS/D Comment	B low profile threshold	I		Estimated	,	Qty	Actual	
# 1	LS/D Comment Material / Labor	B low profile threshold Description / Comment New Door	I	Qty	Estimated	,	Qty	Actual	
# 1	LS/D Comment Material / Labor Unspecified	Description / Comment New Door Incidental Repairs	I	Qty 1	Estimated	,	Qty	Actual	
# 1	LS/D Comment Material / Labor Unspecified Labor	Description / Comment New Door Incidental Repairs	I	Qty 1	Estimated	,	Qty	Actual	
# 1	LS/D Comment Material / Labor Unspecified Labor	Description / Comment New Door Incidental Repairs	I	Qty 1	Estimated	,	Qty	Actual	
# 1	LS/D Comment Material / Labor Unspecified Labor	Description / Comment New Door Incidental Repairs	Units	Qty 1 1	Estimated	,		Actual	

Client Name: Client ID:

Alt. Client ID: 16016SW-0860

DOE Weatherization Assistant

Work Order Name:

Report Run On: 5/24/2010

Work Order (Bid Form)

	Measure 2 Infilt	ration Redctn			Componen	ts			Inspected
Comment									
#	Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
1	Construction	Seal door jam between	Each	1		, ota,			
	Materials/Hardwar e	2 east bedrooms and door jam to back bedrooom. Seal breaker box. Seal ceiling in middle bedroom closet							
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Seal floor to wall in bathroom,around tub, Seal exhaust vent over cook stove and pipes under kitchen sink	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Seal water heater vent and wall by water heater, Seal behind washer and dryer, Repair ceiling in back den approx 2x3 area, Repair 4 spots in hall bath wall	Each	1					
6	Labor	Labor	Hour		1			The state of the s	
7	Construction Materials/Hardwar e	Replace broke glass in E3 window	Each	1		Parameter			
8	Labor	Labor	Hour						
C	Other Detail		r	[1				1
						777 Manuary 1			
			ı	Measur	e Sub Total:		:	Sub Total:	
	Field Notes:								

Client Name: Client ID:

Alt. Client ID: 16016SW-0860

Work Order Name

Work Order (Bid Form)

Report Run On: 5/24/2010

Version 8.5.0 Page 3 of 5

	Measure 3 Attic	: Ins. R-30			Componen	ts A1			Inspected
C	comment Gain acc	cess to attic thru window	in back of	f house					
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - Add 10 inches	SqFt	1006			are in the second secon		
2	Labor	Labor	Hour	1006					
3	Construction Materials/Hardwar e	Remove wet insulation before instaling new insulation	Each	1			THE PROPERTY OF THE PROPERTY O		
4	Labor	Labor	Hour						
C	Other Detail			, , , , , , , , , , , , , , , , , , , ,	punum p	MC 755 - 5 75 75 75 75 75 75 75 75 75 75 75 75 7	, ,	;	
-									
· ·				Measure	Sub Total:			Sub Total:	
The constitution of the co	Field Notes:								
		l Pipe Insulation			Componen				Inspected
С	Measure 4 DWH		Units		Estimated	r	Qtv	Actual	
<i>C</i>	Measure 4 DWH	I Pipe Insulation Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	-		Qty		Inspected Total
<i>C</i> #	Measure 4 DWH omment Material / Labor	Description / Comment		Qty	Estimated	r	Qty	Actual	
C # 1	Measure 4 DWH comment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	r	Qty	Actual	
C # 1	Measure 4 DWH comment Material / Labor Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	r	Qty	Actual	
C # 1	Measure 4 DWH comment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated	r	Qty	Actual	
c # 1	Measure 4 DWH comment Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated	r		Actual	

Client Name:

Client ID:

Alt. Client ID: 16016SW-0860

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 5

Measure 5 CO	Monitor is Needed			Componen	ts		1	nspected
Comment					<u>L</u> 1			
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						The state of the s		
								· · · · · · · · · · · · · · · · · · ·
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 6 Insta	ıll Bathroom Exhaust F	an		Componen Estimated			I Actual	nspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Bathroom exhaust fan	Each	1		Total	w.y		
2 Labor	Labor	Hour	1				1	
Other Detail								
		i	Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	

Client Name:

Client ID:

Alt. Client ID: 16016SW-0860

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/24/2010

Version 8.5.0 Page 5 of 5